

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

DL559
NW
1/2-1
0.849 mi.
4484 ft.

BAY 44TH ST & CROPSEY AVE
BAY 44TH ST & CROPSEY AVE
BROOKLYN, NY

NY Spills **S107407647**
N/A

Site 2 of 3 in cluster DL

Relative:
Higher

Actual:
9 ft.

SPILLS:

Name: BAY 44TH ST & CROPSEY AVE
Address: BAY 44TH ST & CROPSEY AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9900591 / 2000-05-23
Facility ID: 9900591
Facility Type: ER
DER Facility ID: 202543
Site ID: 246649
DEC Region: 2
Spill Cause: Abandoned Drums
Spill Class: C1
SWIS: 2401
Spill Date: 1999-04-15
Investigator: SMSANGES
Referred To: Not reported

Reported to Dept: 1999-04-15
CID: 199
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-04-15
Spill Record Last Update: 2004-11-12
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: 001
Contact Name: ZOLA BAILEY
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND TRANSFERED FROM TIBBE. no drum found"

Remarks: "abandoned drum of unk size found at location - unknown what the material inside is - dep chemist enroute "

All Materials:

Site ID: 246649
Operable Unit ID: 1079353
Operable Unit: 01
Material ID: 307719
Material Code: 0064A
Material Name: unknown material
Case No.: Not reported
Material FA: Other
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported